## Corporate Policy

40		
CARMEUSE		
umber: 250050a		

Policy Name: HAULER SITE SPECIFIC	Section: Loss Prevention	Policy Number: 250050a
	Originator: A1LPM	
Effective Date: January 13, 2010	Revised Date: January	Review Date: January 13,
	13, 2011	2012

## **Carmeuse Lime Inc Hauler Site Hazard Awareness Training-SB PLANT**

Due to the hazards of our operations, haulers will follow all safety rules whether or not posted in work areas. Carmeuse employees have been trained to report any violations of our safety rules. Failure to follow these rules will result in Carmeuse revoking your authorization to drive on our site. Each hauler entering Carmeuse property must receive this training each calendar year by their respective company. Proof of training will be indicated by a hardhat sticker which will be checked regularly. By signing this document you acknowledge you are subject to MSHA and our safety rules and you fully understand and will comply with the following while on Carmeuse property:

## Strasburg MSHA ID: 4400026

	Over the road vehicle operations		Contact any employee for emergency aid. Emergency medical
	U.S Maximum speed limit is 15 mph unless otherwise posted		services number is 911 or your equivalent - Report to the
	Be aware of road conditions and heavy equipment operating in		Scale House
	your immediate vicinity		Haulers are required to report all accidents, injuries, property
	Seat belt usage is mandatory while the vehicle is in motion		damage, and unsafe conditions before leaving the site
ш	Always yield to pedestrians and heavy equipment		Hauler Equipment Operation
	Alarms - signs - postings - directions		Hatches will be closed when entering or exiting our sites
	Obey all alarms, signs, postings, and employee directions		Watch for overhead obstacles (power lines, conveyors, building
	Mandatory personal protective equipment		fixtures) which could be damaged
	ulers will provide and wear their own PPE in all areas of		All open box loads will be tarped before leaving the site
	plant except designated parking areas. PPE includes:		You are not allowed to drive with a dump bed in the up position
	Hardhat – Brim forward		Automatic tarps will not to be removed or placed while truck is in
	Safety glasses - ANSI 287.1 only – dark or mirrored glasses are		motion
	not permitted inside buildings		All dumping must be on a flat level surface to avoid tip over
	Side shields – for prescription glasses		Haulers are not allowed to use or operate any Carmeuse Lime
	Safety toed boots - over the ankle – min 6 inch boot		equipment unless trained. If you need assistance, contact a
	Shirts with sleeves required - Long sleeved suggested		Carmeuse Lime supervisor
	Long pants mandatory – <b>no shorts</b>		Possession of drugs, alcohol, weapons, or firearms is strictly
	Hearing protection as necessary		prohibited
	Respiratory protection must be worn in dusty atmospheres		Headlights must remain on at all times while driving on a
	High visibility vest / clothing		Carmeuse property
	Fall Arrest and Protection		Applicable trucks must use the truck wash facility before leaving
	Full Body Fall Protection Harness – Shall be used when there is		Haulers are prohibited from bringing off site material onto
	a danger of falling- DO NOT climb into the dump bed of the		Carmeuse property.
	truck with out being tied off.		Do not exit the truck while parked on an incline
	You must wear fall arrest equipment while on top of your tanker		Mobile Equipment and Pedestrians
	Your full body harness must fit snugly and not be loose		Always proceed cautiously as heavy equipment operators may
	If using a Carmeuse fall arrest station, attach the lifeline directly		not see you or your vehicle
	to your D-ring, do not use a lanyard		Notify equipment operators before you enter an area where
	Lime, Lime Stone, Rock Dust, and Lime Dust		they are working. Operator must acknowledge your presence
	Lime is a corrosive irritant and will burn skin eyes and nasal		By signing this document you acknowledge:
	passages - always avoid unnecessary contact		You have received this briefing and understand all training items
	Never disturb dust piles or spills	ш	contained therein
	Use dust mask when applicable	П	
	Keep safety glasses properly seated against your face to	ш	,
	prevent lime dust in eyes		regulation(s) whether listed here or not are mandatory at all
	Use water or a dilute vinegar solution flush lime from the skin		times
	Smoking		Failure to comply with any of the aforementioned can result in
	Smoking is prohibited in all buildings, Carmeuse		contractors being immediately ejected from the site and/or
	owned equipment, in the presence of flammable		termination of your contract03/01/2011
	combustible materials, or other designated non		Data.
	smoking areas		Date:
	Slips and Trips		Trainer:
	Wet lime is always slippery - Use handrails, watch where you		
	step, and always use caution when walking on wet surfaces		Trainee's Name Printed:
	Walk around uneven ground or loose stone on catwalks - use		Trainee's Name Printed.
	three point rule exiting heights		Trainco's Company 9. Phono #1
	Hazard Communication (HAZCOM) (WHIMIS)		Trainee's Company & Phone #:
	Chemicals are present in our operations. Blow off at the end of		Trainoo's Signaturo
	your work		Trainee's Signature:
	MSDS Binders are located throughout the site – consult with a		Hard Hat Chicker #1
	Carmeuse employee for more information		Hard Hat Sticker #:

False certification is punishable under section 110(a) and (f) of the Federal Mine Safety and Health Act.

**Emergencies and Evacuations**